Inspection Report

Name of Work: Improvements to drains at 8th B Cross road Difence Colony (Eshwara Temple road) in Ward No 14 Bagalagunte

B.R.No: 1027 **Date:**31.03.2015

Estimate Cost: 10.00 Lakhs

Bill Amount: 839442.00

Date of Inspection 05-03-2016

Observation and Conclusion:

The above said work "Improvements to drains at 8th B Cross road Difence Colony (Eshwara Temple road) in Ward No 41 Bagalagunte" was shown to me by the Concerned AE.

The work is inspected by me along with the Concerned ward Engineer.

The work done is Satisfactory

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Name of Work: Improvements to drains at 8th B cross road Depence colony (Eshwra Temple road) in Bagalagunte Ward No 14

BR No. 1027/14-15, Date.31.12.2015

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of Work: Improvements to drains at 8th B cross road Depence colony (Eshwra Temple road) in Bagalagunte Ward No 14

BR No. 1027/14-15, Date.31.12.2015

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT